Page 1

February 17, 2010 2:37:35 PM

Item ID:

D3783-045

Accept



Setup Start



Revision ID:

Item Name:

Angle Brace Assembly

Start Date: 2/17/10

Required Date: 2/24/10

Start Qty: 4.00 **Req'd Qty:** 4.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date: 10-2-17 Tooling:

Date:

Start

Stop

Stop



QC:

SPC (Y/N):

Date: Date:

Reject

Sequence ID/ **Work Center ID** Operation Description

Pick Kit

Revision Nbr

Set Up/ **Run Hours**

Draw Number

Draw Rev.

Plan Accept Qty Code

Qty

Run

Reject Number Stamp

Draw Nbr

D3783 Rev A

0.00



Packaging

Memo

0.00

Packaging

110

Small Fab

Small Fab

Memo

Memo

0.00

0.00

Small Fab

1-assemble as per dwg D3783

QC5- Inspect part completeness to step on W/O

120

QC

Quality Control

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	GES	· · · · · · · · · · · · · · · · · · · 				
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				· · · · · · · · · · · · · · · · · · ·						
Part No		PAR #:								
<u></u>	Re	solution:							Date:	
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE	(NCR))			
DATE	STEP	Description of NC Section A	Initial			tion B Sign &		ation	Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng		Date				To moposto.

NOTE: Date & initial all entries

Work Order ID 56319

Page 2

February 17, 2010 2:37:35 PM

Item ID:

D3783-045

Accept



Setup Start

Stop



Revision ID:

Item Name:

Angle Brace Assembly

Start Date: Required Date: 2/24/10

2/17/10

QC:

Start Qty: 4.00

Req'd Qty: 4.00



Cust Item ID:

Customer:

Draw

Number

Reference:

Process Plan:

Date:

Date:

Tooling:

Date:

Start

Approvals:

SPC (Y/N):

Date:

Draw

Rev.

Plan

Stop

Reject

Reject

Sequence ID/ **Work Center ID**

130

Packaging

Operation Description

Identify as per dwg & Stock Location: 248

Memo

Memo

0.00

Set Up/

Run Hours

0.00

Code Qty Number

Accept

Run

Insp. Stamp

Packaging

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

10/04/01 HJ

Dart Aerospa	ce L	.td
--------------	------	-----

DATE STEP PROCEDURE CHANGE By Date Qty Chief Er	val Approval
DATE STEP PROCEDURE CHANGE By Date Qty Chief Er	appiovai
Part No: PAR #: Fault Category: NCR: Yes No DQA: Date):
Resolution: Disposition: QA: N/C Closed: Date	:
NCR: WORK ORDER NON-CONFORMANCE (NCR)	
DATE STEP Description of NC Section A Description of NC Section A Initial Action Description Sign & Section C Corrective Action Description Sign & Section C Chief S	
Section A Initial Action Description Sign & Section C Chief Eng Ch	ng QC Inspector

NOTE: Date & initial all entries

Picklist Print February 17, 2010 2:37:39 PM Work Order ID: 56319 D3783-045 Parent Item: Parent Item Name: Angle Brace Assembly



Page 1

Parent Item Name:	Angle Brace Assem	bly	* 100			1 1021		S	tart Date: 2/17	/10	Required Date: 2	/24/10
Comments:	IPP Rev:A 08-05- IPP Rev:B 08-06-				y:EC			:	Start Qty: 4.00		Required Qty: 4	.00
Component Item ID/ Item Name AN5-13A	Replacement Item ID	Mfg/ Purch Purchased	Bin Item No	Primary Location	Last Location	Route Seq ID	Unit of Measure Each	Qty on Hand 64.0000	Remaining Qty To Pick 8.0000	Qty Issued	Date Issued	Status
				<u>Warehor</u>	<u>use</u>	Loc	<u>Qty</u>	Loc Code				
				Loca	<u>ition</u>					,		
				Main Wa	rehouse				M11	418K	8Y	
				ST			64			" " "		
					104936		3		_		-	
					108167 110363		8 14		_		-	
					112492		10		_		-	
AN960JD516 (35IC	n- 1115 1147	900563]	1	113524	113237		29		_		·	
AN960JD516 (JOLC) Washer		Purchased	No	(16X))	110	Each	0.0000	16.0000	510	ps /29	<u></u>
D3765-1 Clevis		Manufactured	No			110	Each	12.0000	8.0000	(Se)	/03/2r	
				Warehou	ise	Loc	<u>Qty</u>	Loc Code				
				<u>Loca</u>	tion							
				Main Wa	rehouse							
				ST			12				-	
					42766		4		_		-	
					54343		B56	421	(Su) -			

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANGE	S				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								••••	
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	_ Date: _	
	Res	solution:	Dispositio	n:	QA: N/C CI	osed:		Date:	
NCR:			WORK ORD	ER NON-CONFORMAI	NCE (NCF	R)	110100		
DATE	STEP Description Section A	Description of NC	Corrective Action Section B Initial Action Description				cation	Approval	Approval
		Section A	Chief Eng	Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector
								-	
				•					
······································									

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE


H:\\TFUHMS\\Quality Assurance\approved QA\\NCRWO RevE

SHOP COPY **RETURN TO ENGINEERING** UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WORK ORDER D3783-041 LATERAL BRACE ASSY DESCRIPTION QTY. (-041) ITEM NO. PART NUMBER TUBE D3769-1 CLEVIS 2 2 D3765-1 BOLT 2 3 AN5-13A NAS1149D0568J WASHER (AN960JD516) 4 5 MS21042L5

NOTES: 1) MATERIAL: N/A 2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: N/A
7) WEIGHT: 0.52 lbs

Α	NEW IS	SUE		HS	08.06.04	
REV.			BY DATE			
DESIGN	I	HS	DART AEROSPA	ACE L	TD	
DRAWN	l	HS	HAWKESBURY, ONTARI	O, CANA	DA	
CHECK	ED	54	DRAWING NO.		REV. A	
MFG. A	PPR.	T.	□ D3783		SHEET 1 OF 3	
APPRO	VED	N.F.	TITLE		SCALE	
DE APPR.			BRACE ASSEMBLY		NTS	
DATE	08.0	06.04	THE DECLARM EN EMPLOYEE ON THE STATE AND CONFIDENTIAL FOR THE STATES OF			

5 4 3 2




DRAWN HS HAWKESBURY, ONTARIO, CANADA DRAWING NO. CHECKED REV. A D3783 MFG. APPR. SHEET 2 OF 3 APPROVED TITLE SCALE BRACE ASSEMBLY

COPYRIGHT © 2008 BY DART AEROSPACE LTD

THE GOODMENT IN PRIVATE AND COMPRETING, AND IS SUPPLIED OF THE LUME ESS CONSTITUTION OF THE LUME OF THE PRIVATE OF THE LUME OF DE APPR. NTS DATE 08.06.04

3



-